






Spare Parts / Ersatzteile / Pièces de recharge / Pezzi di Ricambio / Piezas de requesto /
Parte de reposição / Reserveonderdelen / Reservdelar / Reservedeler / Varaosat /
Vraosat / Varahlutir / Ανταλλακτικά / Yedek Parçalar / Náhradní díly / Náhradné diely /
Nadomestni deli / Резервни части / Запчасти / Części Zapasowe / Pieze de schimb
/ Rendelhető alkatrészek / Запасні частини / Reservni delovi / Резервни делови /
Резервни делови / Atsarginių dalių / Tellitavad varuosad / Rezervju daļu




1
↓
13




XX = AA, AD...

1	A 963 131 NU	22	A 962 391 XX
4	A 963 132 NU	23	A 962 368 NU
8	A 963 143 NU	24	A 962 384 XX
9	A 963 146 NU	25	A 960 895 NU
10	A 963 147 NU	26	A 962 394 XX
13	A 962 594 NU	27	A 961 659 NU
15	A 960 890 NU	29	A 962 388 XX
16	A 960 706 NU	30	A 962 879 XX
17	A 960 891 NU	32	A 962 878 XX
18	A 960 898 NU	33	A 960 704 NU
19	A 960 899 NU		A 962 476 NU
20	A 963 564 NU	34	A 962 475 XX
21	A 963 427 NU		








CERATHERM 200
A 4662 ..

1110 / A 866 282
(+ A 865 612)
Made in Germany



Ideal Standard
Roentgenstrasse 9
54516 Wittlich
Germany





	P	bar		MAX. 10		5			Q	(3 bar)
	T	°C		MAX. 80		65			l/min	30